


PLAN VIEW



NOTES:

- 1.- SEDIMENT TRAPPED UPSTREAM OF SEDIMENT CONTROL BMP SHALL BE REMOVED WEEKLY AND PRIOR TO A RAINFALL EVENT.
- 2.- PLACE BMP'S TIGHTLY TOGETHER AT JOINTS TO PREVENT OR MINIMIZE SEEPAGE AT JOINTS.
- 3.- INLET SEDIMENT CONTROL MUST BE INSPECTED WEEKLY AND AFTER EACH STORM, AND REPAIRED OR REPLACED AS NEEDED.
- 4.- INLET SEDIMENT CONTROL IS REQUIRED FOR ALL DI'S IN ADDITION TO A STORM DRAIN INLET FILTER BAG.

REV.	DATE	DESCRIPTION
△		
△		
△		

R:\Utilstods\City_Std_Details\Wtr_Quality_Details\Q_20_InletSedimentControl.DWG